





P.O. Box 216
4 Ranfurly Street
Otorohanga 3900

Phone: (07) 873-8900
Fax: (07) 873-8905
Email: office@landmore.co.nz

DAIRY MEAL SYSTEM MAINTENANCE

The team here at Landmore Agri Ltd are focused on providing a solid working relationship with you. With this in mind, we would like to offer you two exclusive opportunities for your meal feeding system.

Regular servicing of your meal feeding system is recommended to ensure your system is running efficiently and to minimise unexpected breakdowns. Worn bearings can cause unnecessary drag on your system which can cause snapped augers and burnt out motors.

Anchor Bearing Replacement		Vibrator and Bracket Package for Big Dutchman Silo
This Special Includes:		This Special Includes:
<p><u>Rotary Shed</u></p> <p>Anchor bearing (1) replaced, augers re-tensioned and checked</p> <p>\$95.00 + GST</p>	<p><u>Herring Bone Shed</u></p> <p>Anchor bearings (2) replaced, augers re-tensioned and checked</p> <p>\$190.00 + GST</p>	<p>Mechanical 3 phase power adjustable vibrator and bracket installed to eliminate the problem of feed bridging in the silo hopper</p> <div>   </div> <p>\$800.00 + GST</p>
<p>Please note: mileage, travel time, any worn parts found in the process and extra labour will be an additional charge. While stocks last. <i>Pricing is valid from 17 May 2018 until 30 June 2018.</i></p>		<p>Please note: mileage and travel time will be an additional charge. While stocks last. <i>Pricing is valid from 17 May 2018 until 30 June 2018.</i></p>

Please contact us to book in your anchor bearing replacement, vibrator package and to find out more information on additional services available, including a full meal feeder service.

Kind regards,

Shayne King
Landmore Agri Ltd
M: 027 688 032
Ph: 0508 LANDMORE
E: shaynek@landmore.co.nz